Photo taken by: EPA Region 6
 Date: 11/27/12
 Photo: <u>1</u> of <u>17</u>

**Location:** NLRAP site (AQS #05-119-1002) **Direction:** South of trailer facing north

**Photo of:** the trailer



Photo taken by: EPA Region 6Date: 11/27/12Photo: 2 of 17Location: NLRAP site (AQS #05-119-1002)Direction: outside of the site facing northwest

**Photo of:** the trailer



<b>Photo taken by:</b> EPA Region 6	<b>Date:</b> 11/27/12	<b>Photo:</b> <u>3</u> of <u>17</u>
<b>Location:</b> PARR site (AQS #05-119-0007)	<b>Direction:</b> outside of the site facing southeast	

**Photo of:** the site including two trailers and the platform with the particulate matter (PM) samplers



Photo taken by: EPA Region 6Date: 11/27/12Photo: 4 of 17Location: PARR site (AQS #05-119-0007)Direction: north of the trailer facing southwest

Photo of: the meteorological tower with the NOy convertor box attached



 Photo taken by: EPA Region 6
 Date: 11/27/12
 Photo: <u>5</u> of <u>17</u>

**Location:** PARR site (AQS #05-119-0007) **Direction:** east of the platform facing west

**Photo of:** the particulate matter samplers on the platform



 Photo taken by: EPA Region 6
 Date: 11/27/12
 Photo: 6 of 17

**Location:** PARR site (AQS #05-119-0007) **Photo of:** inside a PM2.5 sampler



 Photo taken by: EPA Region 6
 Date: 11/27/12
 Photo: 7 of 17

**Location:** PARR site (AQS #05-119-0007) **Photo of:** inside a PM2.5 sampler



 Photo taken by: EPA Region 6
 Date: 11/27/12
 Photo: 8 of 17

**Location:** DSR site (AQS #05-119-1008) **Direction:** west of the site facing east

**Photo of:** the site including the trailer and the particulate matter samplers



 Photo taken by: EPA Region 6
 Date: 11/27/12
 Photo: 9 of 17

**Location:** DSR site (AQS #05-119-1008) **Direction:** west of the trailer facing east

Photo of: manifold inlet on the trailer





**Location:** ADEQ Headquarters (Rm 2L07) **Photo of:** Air Lab equipment storage and refrigeration





Photo taken by: EPA Region 6
Location: ADEQ Headquarters (Rm 2L07) **Date:** 11/28/12 **Photo:** 11 of 17

Photo of: Air Lab sample mailing area




**Photo taken by:** EPA Region 6 **Date:** 11/27/12 **Photo:** 12 of 17

**Location:** ADEQ Headquarters (Rm 2L07) Photo of: Air Lab sample mailing area



**Photo taken by:** EPA Region 6 **Date:** 11/28/12 **Photo:** <u>13</u> **of** <u>17</u>

Location: ADEQ Headquarters (Rm 2L08a) Photo of: Air Lab weighing room



**Photo taken by:** EPA Region 6 **Date:** 11/28/12 **Photo:** 14 of 17

**Location:** ADEQ Headquarters (Rm 2L08a) **Photo of:** inside Air Lab weighing room





 Photo taken by: EPA Region 6
 Date: 11/27/12
 Photo: <u>15</u> of <u>17</u>

Location: ADEQ Headquarters (Rm 2L10) Photo of: backup equipment for gaseous instruments





**Photo taken by:** EPA Region 6 **Date:** 11/27/12 **Photo:** <u>16</u> of <u>17</u>

**Location:** ADEQ Headquarters (Rm 2L10) **Photo of:** equipment used to dry out impinger material



Photo taken by: EPA Region 6
Location: ADEQ Headquarters (Rm 2L09)

MAINTENANCE

Francisco Control Con